


Public Works Department
702 Edgebrook Dr.
Champaign, IL 61820
PH 217-403-4710
FAX 217-403-4755

Boneyard Oil Sheen Pollution February 16 & 17, 2011



Legend

— Storm Sewers


Map Date: February 17, 2011



**Photo #1 – Looking east at abandoned railroad bridge.
No discharge from pipe in the east bank of Boneyard.
Photo date: 2/16/2011.**



**Photo #2 – close-up of oil sheen at abandoned railroad bridge.
Photo date: 2/16/2011.**



**Photo #3 – looking down from abandoned railroad bridge.
Oil sheen is coming from the north.
Photo date: 2/16/2011.**



**Photo #4 – oil sheen in Oak-Ash detention basin, just north of the
abandoned railroad bridge.
Photo date: 2/16/2011.**